

Coltrain, Katrina

From: Cook, Brenda

Sent: Friday, March 13, 2015 3:03 PM

To: Coltrain, Katrina

Subject: FW: FW: (b) (6)

From: Cook, Brenda

Sent: Tuesday, February 19, 2013 11:09 AM

To: Ruhl, Christopher

Subject: FW: FW: (b) (6)

Chris,

I reeivedthis from (b) (6) today, have you had a chance to touch base with her.

From: (b) (6)

Sent: Tuesday, February 19, 2013 8:52 AM

To: Cook, Brenda

Subject: RE: FW: (b) (6) /(b) (6)

Brenda,

Any news on my property?

From: Cook.Brenda@epamail.epa.gov [mailto:Cook.Brenda@epamail.epa.gov]

Sent: Tuesday, January 22, 2013 2:19 PM

; Ruhl.Christopher@epamail.epa.gov

Cc: Turner.Ladonna@epamail.epa.gov; Ofosu.Philip@epamail.epa.gov

Subject: Re: FW: (b) (6)

Hi (b) (6)

It was good talking to you on the phone today. As I indicated during our conversation this morning that I have been in communication with OCC and OERB regarding your property. Based on the map that you sent, your property is outside of the boundary of the Wilcox Oil site that EPA and ODEQ are currently investigating. It appears your address may be across the street from the Ohio Refining Site which EPA investigated in 1998/2000 time frame. I am attaching the Site Inspection report and the EPA decision document for Ohio Refining. I touched base with Chris Ruhl and we will continue to look into this for you and respond with more definitive information once it is available. Let me know if you have any additional questions.

Brenda Nixon Cook Region 6 NPL Coordinator 1445 Ross Avenue Dallas, Texas 75202 214-665-7436

Consider being a bone marrow donor!! Join the National Donor Marrow Registry!! For more information visit



www.marrow.org

From: Brenda Cook/R6/USEPA/US@EPA To: Date: 01/16/2013 09:30 AM Subject: FW: Sent by:

Dear Ms. Cook,

I was wondering if you have any information for me regarding the oil on my property. Any help would be greatly appreciated.

Thank you,

From: Ruhl.Christopher@epamail.epa.gov [mailto:Ruhl.Christopher@epamail.epa.gov]

Sent: Tuesday, January 08, 2013 10:19 AM To:(b) (6) Cc: Cook. Brenda@epamail.epa.gov

Subject: (b) (6)

b) (6)

Thanks for sending me your photos. I believe that EPA is in discussions with the Oklahoma Department of Environmental Quality (ODEQ) about the former Wilcox Refinery site. I don't have any information but Brenda Cook is our lead for these discussions and I have cc her on this message. She can be reached at (214) 665-7436.

Chris Ruhl **USEPA Region 6** Oil Team Leader Federal On-Scene Coordinator (214) 665-7356 office

---- Forwarded by Christopher Ruhl/R6/USEPA/US on 01/08/2013 10:01 AM -----

From: Christopher Ruhl/R6/USEPA/US@EPA Date: 01/08/2013 09:39 AM

FW:

Subject: Sent by:

From: (b) (6)

Sent: Wednesday, November 21, 2012 3:58 PM

To: 'ruhl.christopher@epa.gov'

Subject: FW: (b) (6)

2

From: (b) (6)

Sent: Tuesday, November 06, 2012 10:58 AM

To: 'ruhl.christopher@epa.gov'

Subject: FW: (b) (6)

Any news on my property?

Thank you,

(b) (6)

From: (b) (6)

Sent: Thursday, September 27, 2012 7:48 AM


To: 'ruhl.christopher@epa.gov'

Subject: (b) (6)

Christopher,

Here are the picture's and some other information re: my property. I would appreciate any help that you may be able to assist me with.

Thank you,



(LAHOMA DRPORATION COMMISSION P.O. BOX 779

BRISTOW, OK 74010

115 West 6tth Street Telephone: (918 367-3396 FAX: (918) 367-3564

SECT: 20 TWN: 16N RNG: 09E

L AND GAS CONSERVATION DIVISION

TERRY GROOMS Manager, District, I



NOTICE OF REPORT OF INVESTIGATION

May 15, 2009



RE: Complaint #:

18509OGDO12467

Date Received:

May 8, 2009

Leasename WellNbr

NW SW

Location: County:

CREEK

Dear Complainant:

A Corporation Commission representative has investigated the above mentioned complaint.

The findings and recommendations are as follows:

Leavy Grooms

Findings:

CONCRETE AND OLD HYDROCARBON PIT COMING TO THE SURFACE.

Recommendations:

REFER TO OKLAHOMA ENERGY RESOURCES BOARD FOR CLEANUP AND DISMISS.

If there are questions regarding this matter please contact this office at (918)367-3396 .

Sincerely,

CLAHOMA DRPORATION COMMISSION

P.O. BOX 779 BRISTOW, OK 74010

B ANTHONY

nmissioner

115 West 6th Street Telephone: (918 367-3396 FAX: (918) 367-3564

L AND GAS CONSERVATION DIVISION

TERRY GROOMS

Manager, District, I



NOTICE OF COMPLAINT RESOLUTION

May 15, 2009



RE: Complaint #:

18509OGDO12467

Date Received:

May 8, 2009

LeaseNameWellNbr

NW SW

SECT: 20 TWN: 16N RNG: 09E

County:

CREEK

Dear Complainant:

The Corporation Commission resolved the above complaint on May 15,2009 based upon the investigators's findings and recommendations.

The complaint has been referred to the Oklahoma Energy Resources Board as agency of jurisdiction. If there are questions regarding this matter please contact this office at (918)367-3396.

Sincerely, Dury Grooms

4

CLAHOMA DRPORATION COMMISSION

P.O. BOX 779 BRISTOW, OK 74010 115 West 6th Street Telephone: (918 367-3396 FAX: (918) 367-3564

IL AND GAS CONSERVATION DIVISION TERRY

TERRY GROOMS

Manager, District,



NOTICE OF COMPLAINT REFERRAL

May 15, 2009

(b) (6)

(b) (6

(b) (6)

RE: Complaint #:

18509OGDO12467

SECT: 20 TWN: 16N RNG: 09E

Date Received:

May 8, 2009

LeaseNameWellNbr

4 1

Location: SW

County:


CREEK

Dear Complainant:

The Field Operations Department referred the above complaint to Oklahoma Energy Resources Board on May 15,2009 based upon the investigator's findings and recommendations.

The complaint has been referred to the Oklahoma Energy Resources Board as agency of jurisdiction. If there are questions regarding the referred complaint please contact that office.

Sincerely, Surry Lisams







G2012 MapQuest, Inc. Use of directions and maps is subject to the MapQuest Terms of Use. We make no guarantee of the accuracy of their content, road conditions or route usability. You assume all risk of use. View Terms of Use.





UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06

Site Name <u>: Ohio</u>	Oil Company		_ CERCLIS ID	#:OK000198	1349		
Alias Site Names:	1010				i dimensione soluti		
Address: 0.7 mile northeast of Bristow							
City/County or Parish/State/Zip Code: Bristow, Creek County, Oklahoma 74010							
Report Type, Date, a	nd Author: Site Inspectio	n (SI). July 1998.	ODEO				
RECOMMENDAT	ГІОМ	2017 (19910)			WHE SEC 1990 2000		
(X) 1. No Further Re	emedial Action Planned	() 2. Furthe	r Investigation N	leeded Under Sup	perfund		
under Superfund (NFRAP)			() H		Priority: () High		
			SI () R.		() Medium		
			il ()Ri		() Low		
() 3. Action Deferre	ed to:	10 00	perioritied by _				
() RCRA	() NRC						
				5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	material Co.		
NOTIFY AUTHO	DITV.	0.000000					
NOTIFY AUTHO	mir.		*****				
() Removal	() RCRA	() TSCA	() CAA	() SMCRA			
() Remedial	() State	() NPDES	() NRC	() Resource	Trustee:		
() CERCLA Enforce	ment () Federal Facility	() UIC	() SPCC	() Other:			
SEND SSSR COPIES	5 TO:(X) 6SF-AC () 6	WQ-SP () AT	rsdr (X) s	State Agency	() Other		

Site Name:

Ohio Oil Company

CERCLIS ID #: OK0001981349

DISCUSSION:

The Ohio Oil Refinery site is a 101 acre former refinery site. The refinery operated from 1917 until 1942. By 1941, all of the 50,000 gallon storage tanks had been removed from the facility. Potential sources on the site include, 2 former tank berm areas containing asphalt like material, probably tank bottoms, a 13,500 cubic feet waste pit, and several areas of contaminated soil.

The following comments apply to the evaluation of this report:

Ground water in the area is the primary source of drinking water for the City of Bristow. The City obtains its water supply solely from wells that are within the study area. The nearest domestic well is on-site, and several thousand people use wells within a 4 mile radius of the site. However, due to depth of the wells, it is unlikely the wells are impacted. The nearest perennial stream is a ½ mile from the site. Due to minimum source quantities and immobility of waste, migration is unlikely. There are no surface water intakes known to exist along the surface water migration pathway. There are three residences and an eight unit apartment building on-site. There are no schools or day care centers within 200 feet of contaminated areas. There is some evidence of contamination due to the past activities at the site. However, the concentration of contaminants are not significantly high enough to warrant any further evaluation as a potential National Priority List (NPL) site.

The SI report was evaluated considering the requirements of the Hazard Ranking System (HRS), the primary screening tool used by EPA's Superfund program to assess the relative threat associated with actual or potential releases of hazardous substances.

A decision of "No Further Remedial Action Planned" (NFRAP) under Superfund will be entered in CERCLIS, and the site will be referred to the State.

Based upon currently available information, this site fails to meet the minimum criteria required to be included, or proposed, at this time on the NPL by the EPA. The NPL is EPA's list of sites that are priorities for further investigation and, if necessary, response action under CERCLA, 42 USC 960001, et seq. Other actions maybe appropriate under State Authorities.

CONTROL OF THE PROPERTY OF THE		
APPROVALS:	0010	
Report Reviewed by: Philip Ofosu	Signature: Philyofun	Date: Nov/30/99
(Site Assessment Manager 6SF-RA)		
Vicini	C. Austra	ut les
Disposition Recommended by: Susan Webster	Signature: Suran William	Date: 11/3/19
(Team Leader 6SF-RA)	0 00 1	
	X (MILLIAN)	11-100
Disposition Approved by: Charles Gazda/Ragan Broyles	(\$ignature: /////////////	Date: W 3099
(Branch Chief/Deputy Chief 6SF-R)	0 0.0	1.34 -V 288















